

OEI Memo

To: All OEI Powerworks Customers

From: Bob Raisanen/OEI Engineering

Date: 5/4/09

Re: Powerworks Intersection Condition Light Block Tube Change Notice

This memo is to notify all OEI Powerworks Customers the intersection condition light block tube #46.0050.xx has been added to all 180° 2-way, 3-way "T", and 4-way "X", conditions including upholstered and non-upholstery, variable height, full height, and stackable conditions.

This change is due to the rubber light block being eliminated on both sides the universal trim pieces. The added light block tube will eliminate light from passing thru the intersection conditions.

NOTE: The elimination of the universal trim rubber light block will allow for easier Factory upholstery and installation. It will also eliminate the reveal variation on 90° Corners caused by interference between the 2 light blocks on adjoining trim pieces.

Please contact Bob Raisanen 920-2538 with any questions or concerns.

*Thanks,
Bob Raisanen*